# WS90 Firmware V1.4.8 Upgrade 2024-11-28

1. Supports the new T&H module hardware with dual T&H compensation

# WS90 Firmware V1.4.7 Upgrade 2024-09-26

- 1. Optimize the ultrasonic sensor for wind speed measurement.
- 2. Optimize the wind speed algorithm to enhance accuracy.
- 3. Optimize rainfall measurement.

# WS90 Firmware V1.4.3 Upgrade 2024-04-15

1.Optimize wind speed measurement. To ensure accuracy with the upgrade, a recalibration to zero is required for it to take effect.

# WS90 Firmware V1.3.8 Upgrade 2023-10-25

- 1. Optimize wind speed measurement;
- 2. Optimize rainfall measurement;
- 3. Press the CAL button three times in quick succession to toggle the LED on/off.

# WS90 Firmware V1.3.3 Upgrade 2023-04-17

Optimize rain detection algorithm.

# WS90 Firmware V1.3.2 Upgrade 2023-03-29

- 1. Optimized for rain condition wind measurement algorithm, overcome issue that sensor stop reading wind when water comes to the transducer surface.
- 2. Optimized for MODBUS version so that active measurement command is included for faster reading speed. The fastest measurement can be up to 8 sampling per second.
- 3. Battery voltage measurement is possible when heater 12v power is applied for hardware version after v2.0. The early version prior to hardware v2.0 will not be possible to measure battery voltage when 12v external heater power

# WS90 Firmware V1.3.0 Upgrade 2023-01-20

optimize low/no wind speed detection algorithm.

#### WS90 Firmware V1.2.6 Upgrade 2022-09-21

lower drizzle rain detection sensitivity comparing to v1.2.5. For those that 1.2.5 works, then it is no need to upgrade. Only those user that has extra counted during mist rain condition, then this upgrade is recommended.

#### WS90 Firmware V1.2.5 Upgrade

32K XTAL working state check after power on. If no possible for external timing crystal working, switch to internal timing clock, enhancing item robust during different conditions. Increase mist or drizzle rain sensitivity. we recommend most user to set Rain1 gain setting to 0.75 with GW2000 hub or HP25\*\* console series.

Tuning for stormy rain sensitivity alignment.

WS90 Firmware V1.2.3 Upgrade.

Increased sensitivity for mist and drizzle rain detection.

Sensitivity for high rain rate adjusted so that it will have better linearity.

Please reset all rain gain setting to 1.0 after upgrade to this version as the sensitivity for rain detection has been decreased, and please calibrate again if needed.