

WS85 Firmware V1.1.6 Upgrade 2025-9-26

1. Fixed abnormal wind speed measurement bug.

WS85 Firmware V1.1.5 Upgrade 2025-9-22

1. Added automatic wind speed zero-calibration feature in no-wind conditions.

WS85 Firmware V1.1.4 Upgrade 2025-6-3

1. Optimize rainfall measurement to prevent the occurrence of some incorrect rainfall.

WS85 Firmware V1.1.2 Update 2025-03-28

1. Optimized ultrasonic probe anomaly detection.

WS85 Firmware V1.1.1 Update 2025-03-07

1. Optimized LTR390 and LTR380 data processing.

WS85 Firmware V1.0.9 Upgrade 2024-09-27

1. Optimize the ultrasonic sensor for wind speed measurement.
2. Optimize the wind speed algorithm to enhance accuracy.
3. Optimize rainfall measurement.

WS85 Firmware V1.0.8 Upgrade 2024-07-01

1. Optimize the wind speed measurement;