

WS85 Firmware V1.1.2 Update 2025-03-28

1.Optimized ultrasonic probe anomaly detection.

WS85 Firmware V1.1.1 Update 2025-03-07

1.Optimized LTR390 and LTR380 data processing.

WS85 Firmware V1.0.9 Upgrade 2024-09-27

1. Optimize the ultrasonic sensor for wind speed measurement.
2. Optimize the wind speed algorithm to enhance accuracy.
3. Optimize rainfall measurement.

WS85 Firmware V1.0.8 Upgrade 2024-07-01

1.Optimize the wind speed measurement;